



Remover CT

Product description

Remover CT is a non-aggressive mixture, based on natural solvents, suitable for removing fresh adhesive residues and most types of cured contact adhesive. Ideal for removing grease, oils and other dirt residues.

Properties

- High cleaning properties
- High degreasing power
- Multi-purpose use
- Safe in use
- Non corrosive
- Free of aromatic hydrocarbons

Applications

- Removes hard excess contact glue.
- Suitable for removing fresh glue residues, oils, grease and other dirt residues.



Technical data

Base	Mixture based on natural solvents
Consistency	Liquid
Density	ca. 0.85 g/ml
Application temperature	+5°C → +30°C

Application method

- Application method
Shake can well before use. Spray at a distance of appr. 20 cm of the object. Apply as required. Leave to rest for a few minutes. After applying rub the surface dry with a clean towel. Always rub in one direction. Test for adverse effects on the surface in advance.

Health- and Safety Recommendations

Use only in well-ventilated areas.

In case of contact with eyes, wash immediately with plenty of water.

If ingested, rinse mouth thoroughly with running water.

Avoid swallowing the product.

Consult a doctor immediately.

Take the usual labour hygiene into account. Consult the packaging label and safety data sheet for more information.

Dangerous. Respect the precautions for use.

Packaging/Logistics

Colour: Please consult the product catalogue, the Soudal website or a Soudal representative.

Packaging: Please consult the product catalogue, the Soudal website or a Soudal representative.

Shelf life: 2 years in unopened packaging in a cool and dry storage place at temperatures between +5°C and +25°C.



Remover CT

Remarks

- Remover CT allows a primerless application on self-cleaning-glass. (e.g. Activ Glass by Pilkington and Bioclean by Saint-Gobain Glass).
- Greasy residue may remain, this can be removed with Cleaner & Degreaser.
- Remover CT is not suitable to prepare the substrates for bonding. It is not a primer.
- Remover CT can cause staining on porous surfaces.
- Due to the wide variety of possible plastics and paints and to avoid damage to the surface, a preliminary compatibility test is recommended.

This technical data sheet replaces all previous versions. The directives contained in this documentation are the result of our experiments and of our experience and have been submitted in good faith. It is general in nature and does not constitute any liability. Because of the diversity of the materials and substrates and the great number of possible applications which are out of our control, we cannot accept any responsibility for the results obtained. Since the design, the quality of the substrate and processing conditions are beyond our control, no liability under this publication is accepted. It is the responsibility of the user to determine by his own tests whether the product is suitable for the application. In every case it is recommended to carry out preliminary experiments. The manufacturer reserves the right to modify products without prior notice.